

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. **384**

/SAC/2024-25

Date: **14/6/24**


BUILDING SAFETY CERTIFICATE

It is certified that the existing building **Bellwether International School**
(name of the building or premises) at **Keshar Bardi, Mhow, Dist. Indore (MP)**
(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floor(s) in the Block	1	-	-	-	-

The building is owned/occupied by **Bellwether International School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on **14 /06/2024** (date of inspection) in the presence of Manager **Mr. Gaurav Kumar Basediya**, Mhow (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **14 /06/2024** for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on **14 /06/2024** at Indore by **Sub Divisional Officer PWD, Indore.**


Sub Division Officer
PWD Distt. Sub Division No.1, Indore
Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE