

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. 492

/SAC/2025-26

Date : 23/7/2025

Annexure D


BUILDING SAFETY CERTIFICATE

It is certified that the existing building **Bellwether International School** ,
At **Keshar Bardi Mhow** , Dist. Indore (MP) is having block(s)/Floor(s) as per details
below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1	-	-	-	-	-

The building is owned/occupied by **Bellwether International School** have
complied with the Building safety requirements in accordance with National
Building code Rules, and verified by the officers concerned of **Public Work
Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on
23/07/2025 (date of inspection) in the presence of **Manager Mr. Gaurav Kumar
Basediya , Mhow** and that the building/premises is fit for occupancy for running
school with effect from **23/07/2025** for a period of 01 years in accordance with rule
and subject to compliance of the specific conditions as appended.

Issued on **23/07/2025** at Indore by Sub Divisional Officer PWD, Indore


Sub Divisional Officer
PWD Dist. Sub Division No.1, Indore
Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE